



Resources Safety & Health
Queensland

ZERO SERIOUS HARM

Resources Safety & Health

Mackay Office

P.O. Box 1801, Mackay, QLD 4740

Phone: 07 4999 8512, Fax: 07 49998519

Mine Name	Mine ID	Operator	Activity Type	Activity Date
Jupiter Bulk Sample Pit	MI04148	Vulcan Mine Management Pty Ltd	Inspection - Unannounced	29/09/2021

Mine Record Entry

This report forms part of the Mine Record under s68 of the Coal Mining Safety and Health Act 1999. It must be placed in the Mine Record and displayed in 1 or more conspicuous positions at the mine in a way likely to come to the attention of workers at the mine.

Note that inspection or audit activities conducted by the Mines Inspectorate are based upon sample techniques. It remains the primary responsibility of Mine Personnel to identify hazards, and risks associated with Operations and ensure those risks are at an acceptable level.

Today Wednesday 29 September I Michael Scully Inspector of Coal Mines conducted an unannounced inspection of Jupiter Bulk Sample pit.

On arrival I was greeted by Mr Jim McIver (OCE) who escorted me around the mine. Workshop facilities at the mine are limited and consist of a welding bay come warehouse and igloos for servicing mobile plant. The facilities appear to be adequate for the small fleet currently in use.

I conducted an interaction with a CMW engaged in maintenance of a drill rig he was able to demonstrate how he had assessed the hazards relating to his task. I conducted an interaction with a electrician who was repairing a dozer, he also was able to demonstrate how he had assessed the hazards relating to his task. I note that this CMW was doing a particularly good job of managing heat stress.

on completion of my inspection I had a meeting with Mr Michael Cavanagh (SSE). I informed him of my findings and left site.

Michael Scully
Inspector of Mines